

FIG. 1

20045309.0100




FIG. 3






FIG. 4

FIG. 5





20045309.011002

FIG. 7A FIG. 7B FIG. 7C FIG. 7D FIG. 7E FIG. 7F






FIG. 8A FIG. 8B FIG. 8C FIG. 8D




200710" 60E5400T

Localization Uncertainty of 0.1 mm

Without Calibration



With Calibration



Localization Uncertainty of 0.5 mm

Without Calibration




Fig. 10A

With Calibration




Fig. 10B

Localization Uncertainty of 1.0 mm

Without Calibration




Fig. 11A

With Calibration




Fig. 11B

20010"60554001

FIG. 12




Fig. 13 A




Image result without SD calibration

Fig. 13B




Image result with SD calibration